PAGE	

ESG

INVOICE

ORD # 98-02-458

FEB 26 1998

02/21/98 12:58:20

INVOICE # 972000

INVOICE	Milbank Manufacturing Company	REMIT See Below TERMS Net 30 Days
TO	1400 E. Havens	то
	P.O. Box 754	
	Kokomo, IN 46903-0754	
ATTEN	Ronda S. Yeakley	ATTEN Accounts Receivable
		PHONE (317) 290-1471
WORK ID	Effluent Water Composite	
P.C. #	206941	Thank you for your business. We look forward to working with
		you again in the future.
REPORT	Milbank Manufacturing Company	
TO	1400 E. Havens	


RECEIVED 02/16/98 CLIENT MILBANK MFG
REPORTED 02/18/98 PROJECT

Kokomo, IN 46903-0754

P.O. Box 754

ATTEN Ronda S. Yeakley

	ID	CODE	DESCRIPTION		REMARK	PRICE	<u>QTY</u>	DISCOUNT	AMOUNT
TESTS		ZN_IC	Zinc,	ICAPES		 	1		,



## CERTIFICATE OF ANALYSIS

Milbank Manufacturing Company

1400 E. Havens P.O. Box 754

Kokomo, IN 46903-0754 Attn: Ronda S. Yeakley

Purchase Order: 206941

Invoice Number:

Order #: 98-02-458

Date: 02/18/98 14:22

Work ID: Effluent Water Composite

Date Received: 02/16/98 Date Completed: 02/18/98

Client Code: MILBANK MFG

## SAMPLE IDENTIFICATION

Sample

Sample

Number

Description Effluent Water Composite Sample Number Sample

Description

This report may not be reproduced except in full, without the written approval of the laboratory. All results relate only

to the items tested.

This report contains a total number of pages:

Page 2

Order # 98-02-458 02/18/98 14:22

TEST RESULTS BY SAMPLE


Sample: 01AW Effluent Water Composite Collected: 02/13/98 Category: WATER

Test Description Zinc, ICAPES

Result 9.160 <u>Limit</u> 0.010

<u>Units</u> <u>Analyzed</u> By

mg/L 02/18/98 JAR





## ESG soratories

5933 West 71" Street \* Indianapolis, IN 46278 Phone (317) 290-1471 \* Fax (317) 290-1670

## CHAIN OF CUSTODY RECORD

Client Name: ESG Work Order #: 9802458  Project No: Project Name:					ESG Work Order #:		Filtered (Y or N) Presery. Code										Preservation Codes: A = Acld	
						Total												
Sample	r(s),Signatu	ire:	La	la			Number of	/	N/	//	//			//	/ /	//		B = Base C = Cool 4°
Stat.No	DATE	TIME	COMP	GRAB			Containers	$\angle$	$\angle$	$\angle$	$\angle$	$\angle$	_	_	$\leftarrow$	$\angle$	Comments	
	2-13.55	700300			Efflunt	Pit	100	1		ļ				ļ				
															ļ			
															ļ			
														<u> </u>				
								ļ										
					, .													
					,													
								ļ					W	-				
								<u> </u>	. Kaja	٠.				4	1 1		***************************************	
						200							3 - 4 3 - 4					
	- 1																e e e	
							***************************************		-									<del></del>
									-						1.5	7.		
					and the same and t		· · · · · · · · · · · · · · · · · · ·				ţ.							
					^									,				
Relingui	ished By:		Date /	Time	Receifed By:	D	ate / Time	Addit	ional I	nforn	nation:						area and a second a	
550 11				8/98	Scy8 Turn Around Time: Normal Rush Report Due:													
Relinquished By: Date / Time Received By: D				te / Time Are samples suspected to be: Flammable Corrosive Toxic										Toxic 🔲				
							Were samples received intact and properly preserved? Yes No									No 🗀		
Relinquished By: Date / Time Received By:					Da	ite / Time	Temp. Blank°C											